

International Association of Drilling Contractors



ART BOP Controls Subcommittee Meeting

10 September 2014

2:00 – 3:30 pm

IADC

10370 Richmond Ave., Suite 760

Houston, TX 77042

Minutes

- 1) Greetings. See attendance list for meeting
- 2) Review of previous meeting notes. We reviewed the direction that the group previous notes will be delivered to attendee list.
- 3) Peter Skipp prepared a “Purpose” document to Consensus remains: “Recommended Practice Document”.
- 4) Took 2 volunteers to generate sections of the document:
 - a. Tom Cook – “Dirt, Heat, and Shock”
 - b. Dave Dartford – “Maintenance Practices”
- 5) Guidance topics:
 - a. What does success look like?
 - b. What is auditable?
 - c. How to capture data? Strip charts may be considered “outdated”. Recommend real-time electronic capture, transmittal, and storage should be accepted.
 - d. BOP Committee will address both offshore and land rigs.
 - e. Installation and Operations Manual – Define an outline for a manual with content.
 - f. How to make data “useable”. Defining what data to collect is half the battle. Standardize reporting
 - g. Reliability = testing = proof. Redundancy, on its own, does not improve reliability.
 - h. Concentrate on the data and the protocol, not the hardware. Hardware changes, data can be exported.
- 6) Next Meeting – 22 Oct 2014

International Association of Drilling Contractors

Attendance:

Name		Company Name
Jim	Rogers	Chevron
Mick	Stormonth	Environmental Resources Management (ERM)
Scott	Maddox	IADC
David	Dartford	Noble Drilling
Randal	Black	Precision Drilling Oilfield Services Corporation
Brett	Robinson	Proserv Operations
Pete	Skipp	Rockwell Automation
Tom	Cook	Southwestern Controls